



State of Utah

Department of Natural Resources

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:					
OGM	Pete Hess Environmental Scientist III				
Company	Scott Dimick Superintendent				

Inspection Report

Permit Number:	C0070033
Inspection Type:	PARTIAL
Inspection Date:	Friday, July 14, 2006
Start Date/Time:	7/14/2006 12:12:00 PM
End Date/Time:	7/14/2006 1:05:00 PM
Last Inspection:	Thursday, June 15, 2006

Inspector: Pete Hess, Environmental Scientist III

Weather: <u>Sunny</u>; some clouds. <u>Hot.</u> InspectionID Report Number: <u>1014</u>

Types of Operations

Accepted by: whedberg

8/7/2006

Permitee: ANDALEX RESOURCES INC TOWER DIVISION Operator: ANDALEX RESOURCES INC TOWER DIVISION

Site: WILDCAT LOADOUT

Address: 6750 AIRPORT RD, PO BOX 902 PRICE UT 84501

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current	Acrea	aes
---------	-------	-----

100.00	Total Permitted
63.70	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

✓ Federal
 Underground
 State
 County
 ✓ Loadout
 Fee
 ✓ Processing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The Permittee continues to submit quarterly surface water monitoring information as required in Special Permit Condition / Attachment "A" of the current State permit.

The Division Order for the submittal of design drawings and specifications remains pending.

There are no other compliance actions pending.

Inspector's Signature:

Pete Hess, Environmental Scientist III

Date

Wednesday, July 19, 2006

Inspector ID Number: 46

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Inspection Continuation Sheet

Permit Number: C0070033 Inspection Type: PARTIAL

Inspection Date: Friday, July 14, 2006

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
- b. For PARTIAL inspections check only the elements evaluated.
 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers				
3.	Topsoil	✓		✓	
4.a	Hydrologic Balance: Diversions	V			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓			
4.c	Hydrologic Balance: Other Sediment Control Measures	✓		✓	
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓			
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage		✓		
11.	Contemporaneous Reclamation		✓		
12.	Backfilling And Grading		V		
13.	Revegetation		✓		
14.	Subsidence Control		✓		
15.	Cessation of Operations		V		
16.a	Roads: Construction, Maintenance, Surfacing	✓			
16.b	Roads: Drainage Controls	✓			
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	✓			
19.	AVS Check				
20.	Air Quality Permit	✓		V	
21.	Bonding and Insurance				
22.	Other	✓		✓	

Permit Number: C0070033 Inspection Type: PARTIAL

Inspection Date: Friday, July 14, 2006

Page 3 of 3

3. Topsoil

The topsoil pile adjacent to Pond "E" was checked for the presence of wind borne coal fines; none were visible.

4.c Hydrologic Balance: Other Sediment Control Measures

The straw bales which are located in the drainage directly east of Pond "C" are near the end of their usable life. The Permittee should consider replacing these.

4.d Hydrologic Balance: Water Monitoring

Wildcat Wash had no flow in it this day. Only Pond "C" contained a small amount of water.

20. Air Quality Permit

The primary haul roads which were being utilized showed indication that they had been recently watered. Mr. Dimick stated that at least two loads are applied daily in the morning and afternoon. The scale house person keeps track of the water applications in accordance with a requirement in the Air Quality approval order.

22. Other

There has been no change in the status of the CBM well pad for Ritzakis 33-516. There has been no seeding or sediment control implemented at the site.